

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,001,197 B2
DATED : February 21, 2006
INVENTOR(S) : Hiroshi Shirai, Masashi Inoue and Shinichi Hashimoto

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 14.

Line 65, "the upper surface" should be -- the concave upper surface --.

Column 15.

Lines 20 and 24, "metallic reinforcing member" should be -- metallic reinforcing plate --.

Line 62, "the upper surface" should be -- the concave upper surface --.

Column 16.

Lines 18 and 34, "metallic reinforcing member" should be -- metallic reinforcing plate --.


Line 31, "interlocking protrusion" should be -- interlocking portion --.

Line 53, "insulative housing so the land" should be -- insulative housing so that the land --.

Line 59, "the reinforcing plate" should be -- the metallic reinforcing plate --.

Signed and Sealed this

Twenty-third Day of May, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office